RUS Bulletin 1780-18

DAILY INSPECTION REPORT

Job No. 31-018-0810212955 (1)
BCWP -- P1 - 001

Borrower Information
Blackfeet Tribe
Name

Date 7-15, 2003

P. O. Box 2809 Browning Mt. 59417
Street County State Zip

Report No. 70 (2)

Project Information

Type of Project Water intake - BCWP Project Location Lower Two Medicine Lake
Contractor(s) Name Stoddard Construction Superintendent Dean Stoddard

Weather Conditions Clear, 48° & 90°

Description of Work Accomplished The contractor did some minor dozer work around the pit-less units. Groundwater remains at lake-level, which is fairly high at this time. Dozing & cleaning up the work area will continue this week.

Items of Interest Occurred

Delays or Work Restraining Orders

Change Orders

Additional Remarks
(Include problems, delays and controversies on orders)

BY John Monroe
Resident Inspector

Note to Resident Inspector:
The original Daily Inspection report shall be submitted to the borrower at intervals not exceeding one (1) week with copies of the report furnished the project engineer, Contractor(s), and RUS.

(1) Assigned by RUS.
(2) Assigned by Resident Inspector in consecutive order beginning with No. 1.

RUS Bulletin 1780-18

DAILY INSPECTION REPORT

Job No. 31-018-0810212955 (1)
BCWP – P1 - 001

Borrower Information
Blackfeet Tribe
Name

Date 7-18, 2003

P. O. Box 2809 Browning Mt. 59417
Street County State Zip

Report No. 71 (2)

Project Information

Type of Project Water intake - BCWP Project Location Lower Two Medicine Lake
Contractor(s) Name Stoddard Construction Superintendent Dean Stoddard

Weather Conditions Clear 52° & 94°

Description of Work Accomplished Continued dozing & site-grading around the intake pitless units. The reclamation efforts look good at this point.

Items of Interest Occurred

Delays or Work Restraining Orders

Change Orders

Additional Remarks
(Include problems, delays and controversies on orders)

BY John Montoya
Resident Inspector

Note to Resident Inspector:
The original Daily Inspection report shall be submitted to the borrower at intervals not exceeding one (1) week with copies of the report furnished the project engineer, Contractor(s), and RUS.

(1) Assigned by RUS.
(2) Assigned by Resident Inspector in consecutive order beginning with No. 1.

RUS Bulletin 1780-18

DAILY INSPECTION REPORT

Job No. 31-018-0810212955 (1)
BCWP – P1 - 001

Borrower Information
Blackfeet Tribe
Name

Date 7-25, 2003

P. O. Box 2809 Browning Mt. 59417
Street County State Zip

Report No. 72 (2)

Project Information

Type of Project Water intake - BCWP Project Location Lower Two Medicine Lake
Contractor(s) Name Stoddard Construction Superintendent Dean Stoddard

Weather Conditions Partly cloudy 64° & 94°

Description of Work Accomplished The fiber-optic cable has been installed to the intake site. Only minor site grading has been accomplished this past week. Await-delivery of the vault and control building. The contractor plans to set the intake screen next week. Using extreme fire precaution.

Items of Interest Occurred

Delays or Work Restraining Orders

Change Orders

Additional Remarks
(Include problems, delays and controversies on orders)

BY John Monroe
Resident Inspector

Note to Resident Inspector:
The original Daily Inspection report shall be submitted to the borrower at intervals not exceeding one (1) week with copies of the report furnished the project engineer, Contractor(s), and RUS.

(1) Assigned by RUS.
(2) Assigned by Resident Inspector in consecutive order beginning with No. 1.

RUS Bulletin 1780-18

DAILY INSPECTION REPORT

Job No. 31-018-0810212955 (1)
BCWP – P1 - 001

Borrower Information
Blackfeet Tribe
Name

Date 7 - 31, 2003

P. O. Box 2809 Browning Mt. 59417
Street County State Zip

Report No. 73 (2)

Project Information

Type of Project Water intake - BCWP Project Location Lower Two Medicine Lake
Contractor(s) Name Stoddard Construction Superintendent Dean Stoddard

Weather Conditions Hazey & smokey 61° & 93°

Description of Work Accomplished The contractor has the intake site well graded and awaiting delivery of the concrete underground vault and control building. Excavation will soon begin to connect the intake piping (P1-001) to the (P1-002) piping that leads to the treatment plant.

Items of Interest Occurred

Delays or Work Restraining Orders Stage II fire restrictions imposed on 7-28-03

Change Orders

Additional Remarks
(Include problems, delays and controversies on orders)

Stage II ~ work only from 1:00 A.M. to 1:00 P.M. "Hoot Owl hrs.".

BY John Monroe
Resident Inspector

Note to Resident Inspector:
The original Daily Inspection report shall be submitted to the borrower at intervals not exceeding one (1) week with copies of the report furnished the project engineer, Contractor(s), and RUS.

(1) Assigned by RUS.
(2) Assigned by Resident Inspector in consecutive order beginning with No. 1.