

DAILY INSPECTION REPORT

Job No. 31-018-0810212955 (1)
BCWP - P1 - 001

Borrower Information

Name Blackfoot Tribe Date 11-25, 2002
P. O. Box 2809 Browning Mt. 59417 Report No. 57 (2)
Street County State Zip

Project Information

Type of Project Water intake - BCWP Project Location Lower Two Medicine Lake
Contractor(s) Name Stoddard Construction Superintendent Dean Stoddard

Weather Conditions partly cloudy +14° & +90°

Description of Work Accomplished The cofferdam has been sealed from sloughing and final grade reached inside. The 20" casings are in final position. Pumping ground water 24 hrs/day. Pouring the manifold support pad and concrete cell seal is scheduled for this or next week.

Items of Interest Occurred _____

Delays or Work Restraining Orders _____

Change Orders _____

Additional Remarks _____
(Include problems, delays and controversies on orders)

BY John Montoye
Resident Inspector

Note to Resident Inspector:
The original Daily Inspection report shall be submitted to the borrower at intervals not exceeding one (1) week with copies of the report furnished the project engineer, Contractor(s), and RUS.

- (1) Assigned by RUS.
- (2) Assigned by Resident Inspector in consecutive order beginning with No. 1.